


Auto-Off Feature:

- After 5 minutes in any mode, warning mode pulse will activate.
- After 1 minute in warning pulse mode, laser will turn off.
- Press the switch during warning pulse for laser reset.



Batteries: 2 A-76 batteries

- Batteries can be changed with laser installed on gun!
- Use .050 hex key to remove battery cover.
- Insert 2 A-76 batteries (+ side up).
- Note: Dimple on battery cover must be face down.
- Tighten down the battery cover, and check periodically.



WARRANTY:
One Year Limited
Warranty.



LASERLYTE
30 N. Alamos Drive - Cottonwood, AZ 86326
Phone 928-649-3201 - Fax 928-649-3970
www.LaserLyte.com

CE
RoHS

REV312



**BERSA® THUNDER .380
LASER**



- Fits Bersa Thunder .380 & .380 Plus
- Quick and Easy installation
- Works with nylon holsters
 - Blackhawk® #7
 - Uncle Mike's® #15
- Ergonomic activation
- Dual laser modes with auto-off feature

CK-MS

BERSA® THUNDER .380 LASER

www.LASERLYTE.com



